


1	2	3	4	5	6	7	8	
A								A
B								B
C								C
D								D
E								E
F								F
G								G
H								H
1	2	3	4	5	6	7	8	

PP100JAR:Dタイプ印刷範囲



印刷始めと終わりは7mm空けて下さい。

F

E

D

C

B

A

F


E

D

C

B

A



PP100CAP印刷範囲

社 外 秘						容量	O.F	mL	重量	g
品 名						材質		尺度		
						製図		N.Arai	検図	
成形				取数	CAV	△3				
機種				図番		△2				
／	製品一般寸法公差					△1				
寸法(mm)	1~4	5~10	11~25	26~63	64~100	101~400	AAIM'S株式会社アライ化成			
公差(mm)	±0.1	±0.15	±0.2	±0.3	±0.5	±1.2				
									A3	



A3